



September 10, 2026

Move-out Inspection

Inspection label:

Move-out for 6286 Meadowbank Ln

Completed by:

Kakhramon Pulatov

kpulatov@gmail.com

Completed on:

September 10, 2026

Address:

6286 Meadowbank Ln, Colorado Springs 80925

Summary

Content	Rating Percentage	Good	Fair	Poor	Flags	Link
Table of Contents						🔗
Front Door		0% Good	0% Fair	100% Poor		🔗
Living Room		0% Good	0% Fair	100% Poor		🔗
Dining Room		0% Good	0% Fair	100% Poor		🔗
Kitchen		0% Good	0% Fair	100% Poor		🔗
Hallway		0% Good	0% Fair	100% Poor		🔗
Stairway		0% Good	0% Fair	100% Poor		🔗
First Bedroom		0% Good	0% Fair	100% Poor		🔗
Second Bedroom		0% Good	0% Fair	100% Poor		🔗
Third Bedroom		0% Good	0% Fair	100% Poor		🔗
Fourth Bedroom		0% Good	0% Fair	100% Poor		🔗
First Full Bathroom		0% Good	0% Fair	100% Poor		🔗
Second Full Bathroom		0% Good	0% Fair	100% Poor		🔗
First Half Bathroom		0% Good	0% Fair	100% Poor		🔗
Laundry Room		0% Good	0% Fair	100% Poor		🔗
Office		0% Good	0% Fair	100% Poor		🔗
Storage Room		0% Good	100% Fair	0% Poor		🔗
Loft		0% Good	0% Fair	100% Poor		🔗
Garage		0% Good	0% Fair	100% Poor		🔗
General		0% Good	0% Fair	100% Poor		🔗
Back Door		0% Good	0% Fair	100% Poor		🔗
Patio		0% Good	0% Fair	100% Poor		🔗
Exterior		0% Good	0% Fair	100% Poor		🔗

Table of Contents

Room/Area	Feature	Maintenance	Images	Rating	View
Front Door	Front Door		3	 Poor	View
Living Room	Living Room		2	 Poor	View
Dining Room	Dining Room		3	 Poor	View
Kitchen	Kitchen		10	 Poor	View
Hallway	Hallway		3	 Poor	View
Stairway	Stairway		3	 Poor	View
First Bedroom	Bedroom		2	 Poor	View
Second Bedroom	Bedroom		5	 Poor	View
Third Bedroom	Bedroom		6	 Poor	View
Fourth Bedroom	Bedroom		2	 Poor	View
First Full Bathroom	Full Bathroom		2	 Poor	View
Second Full Bathroom	Full Bathroom		2	 Poor	View
First Half Bathroom	Half Bathroom		1	 Poor	View
Laundry Room	Laundry Room		4	 Poor	View
Office	Office		2	 Poor	View
Storage Room	Storage Room		1	 Fair	View
Loft	Loft		3	 Poor	View
Garage	Garage		4	 Poor	View
General	General		1	 Poor	View
Back Door	Back Door		2	 Poor	View
Patio	Patio		1	 Poor	View

Room/Area	Feature	Maintenance	Images	Rating	View
Exterior	Exterior		19	Poor	👁

Front Door

Front Door

Images

Rating

3

Poor



[View Image](#)



[View Image](#)



[View Image](#)

Living Room

Living Room

Images

2

Rating

Poor



[View Image](#)



[View Image](#)

Dining Room

Dining Room

Images

Rating

3

Poor



[View Image](#)



[View Image](#)



[View Image](#)

Kitchen

Kitchen

Images

Rating

10

Poor



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)




[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)

Hallway

Hallway

Images

3

Rating

Poor



[View Image](#)



[View Image](#)



[View Image](#)

Stairway

Stairway

Images

Rating

3

Poor



[View Image](#)



[View Image](#)



[View Image](#)

First Bedroom

Bedroom

Images

2

Rating

Poor



[View Image](#)



[View Image](#)

Second Bedroom


Bedroom

Images


Rating

5

Poor



[View Image](#)




[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)

Third Bedroom
Bedroom

Images

6

Rating


Poor



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)

Fourth Bedroom
Bedroom

Images

Rating

 2

 Poor



[View Image](#)



[View Image](#)

First Full Bathroom

Full Bathroom

Images

2

Rating

Poor



[View Image](#)



[View Image](#)

Second Full Bathroom

Full Bathroom

Images

2

Rating

Poor



[View Image](#)



[View Image](#)

First Half Bathroom

Half Bathroom

Images

Rating

 1

 Poor



[View Image](#)

Laundry Room

Laundry Room

Images


Rating

4

Poor



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)

Office

Office

Images

Rating

2

Poor



[View Image](#)



[View Image](#)

Storage Room

Storage Room

Images

1

Rating

Fair



[View Image](#)

Loft

Loft

Images

Rating

3

Poor



[View Image](#)



[View Image](#)



[View Image](#)

Garage

Garage

Images

Rating

4

Poor



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)

General

General

Images

1

Rating

Poor



[View Image](#)

Back Door

Back Door

Images

2

Rating

Poor



[View Image](#)



[View Image](#)

Patio

Patio

Images

1

Rating

Poor



[View Image](#)

Exterior

Exterior

Images

Rating

19

Poor



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)



[View Image](#)

Inspection completed

By adding your signature, you agree that this inspection is current, accurate, and complete to your knowledge.



Kakhramon Pulatov
Landlord
Signed on 9/10/2026

